Ultra-compact CMOS Smart Laser Sensor

E3NC-S

CSM_E3NC-S_DS_E_6_1

A Ultra-compact CMOS Laser Sensor for Stable Detection without the Influence of Workpiece Color, Material, or Surface Conditions

- Dynamic range of 500,000 times for stable detection without influence from changes in workpieces.
- The industry's smallest CMOS laser head* for installation into small spaces.
- Distance discrimination enables stable detection of level differences as small as 1.5 mm.
- Robot cable for reliable application in adverse environments and IP67 protection.
- White on black display characters for high visibility.
- Smart Tuning to achieve stable detection with easy setup.

* Based on November 2012 OMRON investigation.



Refer to the Safety Precautions on page 8.



For the most recent information on models that have been certified for safety standards, refer to your OMRON website.

Ordering Information

Sensor Heads (Dimensions → page 10)

Appearance	Sensing distance	Model	Laser class
	35 to 250 mm	E3NC-SH250H 2M	Class 2
	35 to 250 min	E3NC-SH250 2M	
	35 to 100 mm	E3NC-SH100 2M	Class 1

Amplifier Units (Dimensions → page 10)

Connecting method	Appearance	Inputs/outputs	Mo	del
Connecting method	Appearance inputs/outputs		NPN output	PNP output
Pre-wired (2 m)		2 outputs + 1 input	E3NC-SA21 2M	E3NC-SA51 2M
Wire-saving Connector		1 output + 1 input	E3NC-SA7	E3NC-SA9
M8 Connector	and the same of th	1 output + 1 input	E3NC-SA24	E3NC-SA54
Connector for Sensor Communications Unit *			E3NC-SA0	

^{*}A Sensor Communications Unit is required if you want to use the Amplifier Unit on a network.

Accessories (Sold Separately)

Sensor Head Accessories

Sensor Head Mounting Brackets

A Mounting Bracket is not provided with the Sensor Head. It must be ordered separately as required. (Dimensions → page 12)

Applicable Sensor Head	Appearance	Model	Quantity	Contents
E3NC-SH250H		E39-L187	1	Mounting Bracket: 1
E3NC-SH250 E3NC-SH100		E39-L188	1	Nut plate: 1 Phillips screws (M3×18): 2

Amplifier Unit Accessories

Wire-saving Connectors (Required for models for Wire-saving Connectors.) (Dimensions → page 14)

Connectors are not provided with the Amplifier Unit and must be ordered separately. *Protective stickers are provided.

Туре	Appearance	Cable length	No. of conductors	Model
Master Connector	*	- 2 m	4	E3X-CN21
Slave Connector	*		2	E3X-CN22

Sensor I/O Connectors (Required for models for M8 Connectors.) (Dimensions → page 14)

Connectors are not provided with the Fiber Amplifier Unit and must be ordered separately.

Size	Cable	Appearance		Cable	e type	Model	
		Straight		2m		XS3F-M421-402-A	
M8	Standard cable	Straight			5m	4	XS3F-M421-405-A
IVIO	Standard Cable	L-shaped			2m	4-wire	XS3F-M422-402-A
				5m		XS3F-M422-405-A	

Amplifier Unit Mounting Bracket (Dimensions → page 15) A Mounting Bracket is not provided with the Amplifier Unit. It must be ordered separately as required.

	. ,	
Appearance	Model	Quantity
	E39-L143	1

DIN Track (Dimensions → page 15)

A DIN Track is not provided with the Amplifier Unit. It must be ordered separately as required.

Appearan ce	Туре	Model	Quantity
	Shallow type, total length: 1 m	PFP-100N	
	Shallow type, total length: 0.5m	PFP-50N	1
	Deep type, total length: 1 m	PFP-100N2	

End Plate (Dimensions → page 15)

Two End Plates are provided with the Sensor Communications Unit. End Plates are not provided with the Amplifier Unit. They must be ordered separately as required.

Appearance	Model	Quantity
	PFP-M	1

Related Products

Sensor Communications Units

Туре	Appearance	Model
Sensor Communications Unit for EtherCAT		E3NW-ECT
Sensor Communications Unit for CompoNet *1		E3NW-CRT
Sensor Communications Unit for CC-Link *1	000	E3NW-CCL
Distributed Sensor Unit *2		E3NW-DS

***1.** Refer to your OMRON website for details.

*2. The Distributed Sensor Unit can be connected to any of the Sensor Communications Units.

EtherCAT® is a registered trademark and patented technology, licensed by Beckhoff Automation GmbH, Germany. CompoNet is a registered trademark of the ODVA. CC-Link is a registered trademark of Mitsubishi Electric Corporation. The trademark is managed by the CC-Link Partner Association.

Ratings and Specifications

Sensor Heads

	Sensing method		Distance-settable			
Item	Model	E3NC-SH250H	E3NC-SH250	E3NC-SH100		
Light source (wavelength)*1		Visible semiconductor laser diode (660 nm), 1 mW (average output: 220 μW) (JIS Class 2, IEC/EN Class 2, and FDA Class 2)				
Measurement range		35 to 250 mm (display value: 350	to 2,500)	35 to 100 mm (display value: 350 to 1,000)		
Standard de	etected level difference	35 to 180mm: 9 mm 180 to 250 mm: 25 mm		35 to 50 mm: 1.5 mm 50 to 100 mm: 3 mm		
Spot diame	ter*3	Approx. 1 mm (at 250 mm)		Approx. 0.5 mm (at 100 mm)		
Indicators OUT indicator (orange), STABILITY indicator (green), and ST indicator (blue)				or (blue)		
Ambient illumination		Illumination on received light surface: 4,000 lx max. of incandescent light, 8,000 lx max. of sunlight	Illumination on received light surface: 2,000 lx max. of incandescent light, 4,000 lx max. of sunlight	Illumination on received light surface: 4,000 lx max. of incandescent light, 8,000 lx max. of sunlight		
Ambient ter	nperature range	Operating: -10 to 50°C; Storage: -25 to 70°C (with no icing or condensation)				
Ambient hu	midity range	Operating and storage: 35% to 85% (with no condensation)				
Insulation r	esistance	20 MΩ min. (at 500 VDC)				
Dielectric s	trength	1,000 VAC at 50/60 Hz for 1 min				
Vibration re	esistance (destruction)	10 to 55 Hz with a 1.5-mm double amplitude for 2 hours each in X, Y, and Z directions				
Shock resis	stance (destruction)	500 m/s ² 3 times each in X, Y, and Z directions				
Degree of p	rotection	IEC IP67				
Connecting	method	Pre-wired connector (Standard cable length: 2 m)				
	Case	Polybutylene terephthalate (PBT)				
Materials	Lens	Methacrylic resin				
	Cable	PVC				
Weight (pad	ked state/Sensor Head	Approx. 125 g/approx. 75 g				
Accessorie	s	Instruction Manual, laser warning label (E3NC-SH250H only)				

Note: Incorrect detection may occur outside the measurement range if the object has a high reflection factor.

Also, when detecting a workpiece that is smaller than the spot diameter, a correct value may not be obtained.

^{*1.} These Sensors are classified as Class 1 laser devices under IEC 60825-1 and the regulations of Laser Notice No. 50 for FDA certification.

CDRH (Center for Devices and Radiological Health) registration has been completed. (Accession Number:1220691)

^{*2.} The values were measured at the center of the sensing distance using OMRON's standard sensing object (white ceramic).

^{*3.} Spot diameter: Defined at the 1/e² (13.5 %) of the central intensity at the measurement distance.

Measurement may be influenced if there is light leakage outside the defined region and the surroundings of the target object have a high reflectance in comparison to the target object.

Amplifier Units

		Туре		Standard models		Model for Sensor Communications Unit		
		NPN output	E3NC-SA21	E3NC-SA7	E3NC-SA24			
		PNP output	E3NC-SA51	E3NC-SA9	E3NC-SA54	E3NC-SA0		
lí	em	Connecting method	Pre-wired Wire-saving Connector M8 Connector		Connector for Sensor Communications Unit			
Inputs/	Outputs		2 outputs	1 output		#1		
outputs	External inputs	s	1 input					
Power supply	voltage		10 to 30 VDC, including 1	10% ripple (p-p)				
Power consun	nption *2		At Power Supply Voltage Normal mode: 1,920 m Power saving eco mode	W max. (Current cons		mA max.)		
			Load power supply voltage Load current: Groups of of 4 to 30 Amplifier Units:	1 to 3 Amplifier Units:	n-collector output 100 mA max., Groups			
Control outpu	ts *3		Residual voltage: At load current of less At load current of 10 t		κ.)	-		
.			OFF current: 0.1 mA max.	-				
External input	s		Refer to *4.			1.16. \		
Indicators			7-segment displays (Sub Display direction: Switcha OUT indicator (orange), I selection indicator (orang	able between normal _/D indicator (orange)	and reversed. , ST indicator (blue), Zf	rhite) ERO indicator (green), and OUT		
Protection circuits		Power supply reverse polarity protection, output short-circuit protection, and output reverse polarity protection			Power supply reverse polarity protection and output short-circui protection			
Super-high-speed mode (SHS) *5		Operate or reset: 1.5 ms						
-	High-speed mo	ode (HS)	Operate or reset: 5 ms					
time	Standard mode	e (Stnd)	Operate or reset: 10 ms					
	Giga-power mo	ode (GIGA)	Operate or reset: 50 ms					
Sensitivity adj	ustment		Smart Tuning (2-point tuning, full auto tuning, 1-point tuning, tuning without workpiece, 2-point area tuning, 1-point area tuning, or area tuning without workpiece), or manual adjustment					
	Super-high-sp	eed mode (SHS) *5	0					
No. of Units for mutual	High-speed mo	ode (HS)	2					
interference	Standard mode	e (Stnd)	2					
prevention	Giga-power mo	ode (GIGA)	2					
	Timer		Select from timer disable	d, OFF-delay, ON-del	ay, one-shot, or ON-de	lay + OFF-delay timer: 1 to 9,999 n		
	Zero reset		Negative values can be o	lisplayed. (Threshold	value is shifted.)			
	Resetting setti	ings *6	Select from initial reset (f	actory defaults) or us	er reset (saved settings	3).		
	Eco mode		Select from OFF (digital of	displays lit) or ECO (c	igital displays not lit).			
	Bank switching	g	Select from banks 1 to 4.					
	Output 1		Select from Normal detec	ction mode, Area dete	ction mode, or hold mo	ode.		
Functions	Output 2		Select from Normal detection mode or Error output mode.			Select from Normal detection mode or Error output mode.		
	External input		Select from input OFF, tuning, laser OFF, zero reset, or bank switching.					
	Keep function	* 7	Select from ON or OFF.			•		
	Background si	uppression *8	Select from ON or OFF.					
	Hysteresis wid	ith	Select from standard sett	ing or user setting.				

*1. Two sensor outputs are allocated in the programmable logic controller PLC I/O table.
PLC operation via Communications Unit enables reading detected values and changing settings.

*2. At Power Supply Voltage of 10 to 30 VDC.
Normal mode: 2.250 mW max. (Current consumption: 75 mA max. at 30 VDC, 145 mA max. at 10 VDC)
Power saving eco mode: 1,950 mW max. (Current consumption: 65 mA max. at 30 VDC, 125 mA max. at 10 VDC)

*3. The total for both outputs of a model with 2 outputs is 100 mA max. (Residual voltage: Load current of less than 10 mA: 1 V max., Load current of 10 to 100 mA: 2 V max.) V max.). *4. The following details apply to the input.

		Contact input (relay or switch)	Non-contact input (transistor)	Input time
N	IPN		ON: 1.5 V max. (Sourcing current: 1 mA max.) OFF: Vcc – 1.5 V to Vcc (Leakage current: 0.1 mA max.)	ON: 9 ms min.
P	NP	,	ON: Vcc – 1.5 V to Vcc (Sinking current: 3 mA max.) OFF: 1.5 V max. (Leakage current: 0.1 mA max.)	OFF: 9 ms min.

^{*5.} The mutual interference prevention function is disabled if the detection mode is set to super-high-speed mode.

*6. The bank is not reset by the user reset function or saved by the user save function.


*7. The output for a measurement error is set. ON: The value of the output from before the measurement error is retained. OFF: The output is turned OFF when a measurement error occurs.

*8. Only the sensing object is detected when tuning.


	Туре	Standard models			Model for Sensor Communications Unit	
	NPN output	E3NC-SA21	E3NC-SA7	E3NC-SA24	E3NC-SA0	
	PNP output	E3NC-SA51	E3NC-SA9	E3NC-SA54	E3NC-SAU	
Item	Connecting method	Pre-wired	Wire-saving Connector	M8 Connector	Connector for Sensor Communications Unit	
Maximum connectable Units		30				
Ambient temperature range		Operating: Groups of 1 or 2 Amplifier Units: -25 to 55°C, Groups of 3 to 10 Amplifier Units: -25 to 50°C, Groups of 11 to 16 Amplifier Units: -25 to 45°C, Groups of 17 to 30 Amplifier Units: -25 to 40°C Storage: -30 to 70°C (with no icing or condensation)			Operating: Groups of 1 or 2 Amplifier Units: 0 to 55°C, Groups of 3 to 10 Amplifier Units: 0 to 50°C, Groups of 11 to 16 Amplifier Units: 0 to 45°C, Groups of 17 to 30 Amplifier Units: 0 to 40°C Storage: –30 to 70°C (with no icing or condensation)	
Ambient humidity range		Operating and storage: 35% to 85% (with no condensation)				
Insulation resistance		20 MΩ (at 500 VDC)				
Dielectric strength		1,000 VAC at 50/60 Hz for 1 min				
Vibration resistance (destruction)		10 to 55 Hz with a 1.5-mm double amplitude for 2 hours each in X, Y, and Z directions				
Shock resistance (destruction)		500 m/s² for 3 times each in X, Y, and Z directions			150 m/s² for 3 times each in X, Y, and Z directions	
Weight (packed state/Amplifier Unit only)		Approx. 115 g/approx. 75 g	Approx. 60 g/ approx. 20 g	Approx. 65 g/approx	. 25 g	
Materials	Case	Polycarbonate (PC)				
	Cover	Polycarbonate (PC)				
	Cable	PVC				
Accessories		Instruction Manual				

Engineering Data (Reference Value)

Spot Diameter Vs. Distance E3NC-SH250/SH250H



E3NC-SH100




I/O Circuit Diagrams

NPN Output


Model	Operation mode	Timing chart	L/D indicator	Output circuit
E3NC-SA21	Light-ON	ch1/ Incident light ch2 No incident light OUT indicator Lit (orange) Not lit Output ON transistor OFF Load Operate (e.g., relay) Reset (Between brown and black (orange) leads)	L lit.	Display OUT1 indicator OUT2 indicator Display (orange) Brown Black Control output Load Orange ch1 10 to
	Dark-ON	ch1/ Incident light ch2 No incident light OUT indicator Lit (orange) Not lit Output ON transistor OFF Load Operate (e.g., relay) Reset (Between brown and black (orange) leads)	D lit.	Photoelectric sensor main circuit Pink External Blue Photoelectric sensor main circuit Blue Pink External
E3NC-SA7 E3NC-SA24	Light-ON	Incident light No incident light OUT indicator Lit (orange) Not lit Output ON transistor OFF Load Operate (e.g., relay) Reset (Between brown and black leads)	L lit.	Display OUT indicator (orange) Black Control output 10 to 91000 Photoelectric sensor main clouit Pink
	Dark-ON	Incident light No incident light OUT indicator Lit (orange) Not lit Output ON transistor OFF Load Operate (e.g., relay) Reset (Between brown and black leads)		sersor main circuit Pink External input

PNP Output




Nomenclature

E3NC-SA21/SA51/SA0



E3NC-SA7/SA9/SA24/SA54



Safety Precautions

To ensure safe operation, be sure to read and follow the Instruction Manual provided with the Sensor.

Sensor Heads

Laser Safety

Various safety standards regarding laser devices are stipulated in Japan and abroad. When this Sensor Head is used in Japan and when it is assembled in Japan but exported to a foreign country, the safety standards are classified into three cases.

When Using the Sensor Head in Japan
JIS C6802 stipulates the safety measures that must be observed by
the user for each type of laser equipment.

E3NC-SH□□ Sensor Heads: Class 1 E3NC-SH□□H Sensor Heads: Class 2



Do not expose your eyes to the laser beam either directly or indirectly (i.e., after reflection from a mirror or shiny surface). The laser beam has a high power density and exposure may result in loss of sight.



Do not disassemble the Sensor Head. Doing so may cause the laser beam to leak, resulting in a risk of visual impairment.



 The E3NC-SH has the following WARNING label or explanatory label on the side of the sensors.









When using devices in which E3NC-SH is installed in the U.S.
 The devices are subjected to the U.S. FDA (Food and Drug
 Administration) laser regulations. E3NC-SH series is classified
 into Class 1 or Class 2 by the standard of IEC/EN60825-1
 according to deviations of Laser Notice NO.50 of this standard,
 and is

already reported to CDRH (Center for Devices and Radiological Health). Accession Number 1220691

For countries other than Japan
Replace the WARNING label with the corresponding English
label. (supplied with SH□□H) Please make sure that the label is
affixed at the correct locations as indicated.

Using in Europe
 The E3NC-SH is categorized as a Class 1 or Class 2 device as stipulated in EN60825-1.

Precautions for Safe Use

The following precautions must be observed to ensure safe operation of the Sensor Head.

- 1. Installation Environment
- Do not use the Sensor Head in an environment where explosive or flammable gas is present.
- To secure the safety of operation and maintenance, do not install the Sensor Head close to high-voltage devices or power devices.
- 2. Power Supply and Wiring
- Always use an E3NC-SA \(\subseteq \), or E3NC-SAO Amplifier Unit. If a different Amplifier Unit is used, damage or fire may occur.
- If you short the cable, reconnect it as specified. If the connections are not correct, damage or fire may occur.
- High-voltage lines and power lines must be wired separately from the Sensor Head. Wiring them together or placing them in the same duct may cause induction, resulting in malfunction or damage.
- Always turn OFF the power supply before connecting or disconnecting the connectors.

- 3. Installation
- During installation, tighten the screws securely, but do not exceed the specified tightening torque.
 Specified torque (M3): 0.5 N·m
- 4. Others
- Never disassemble, repair, modify, deform by pressure, or incinerate the Sensor Head.
- Dispose of the Sensor Head as industrial waste.
- If you notice any abnormalities, immediately stop using the Sensor Head, turn OFF the power supply, and contact your OMRON representative.

Precautions for Correct Use

Observe the following precautions to prevent failure to operate, malfunctions, or undesirable effects on Sensor Head performance.

1. Installation Environment


Do not install the Sensor Head in locations subject to the following conditions:

- · Ambient temperatures outside of the rated range
- Condensation caused by rapid changes in temperature
- Relative humidity that is not between 35% and 85%
- · Corrosive or flammable gas
- · Dust, salt, or iron particles
- · Direct vibration or shock
- Strong external light interference (such as other laser beams or electric arc-welding machines)
- · Direct sunlight or near heaters
- · Water, oil, or chemical fumes or spray
- · Strong magnetic or electric fields
- 2. Warming Up
- For accurate measurements, allow the product to stand for at least 10 minutes after turning ON the power supply before use.
- The circuits will be unstable just after the power supply is turned ON, so measurement values may fluctuate gradually.
- 3. Maintenance and Inspection
- Always turn OFF the power supply before adjusting or connecting/ disconnecting the Sensor Head.
- Do not use thinner, benzene, acetone, or kerosene to clean the Sensor Head.
- If large dust particles or dirt adheres to the filter on the front of the Sensor Head, use a blower brush (such as one used to clean camera lenses) to blow it off. Do not blow the dust particles or dirt with your mouth. To remove dust particles or dirt, wipe it off gently with a soft cloth (such as one for cleaning lenses) moistened with a small amount of alcohol. Do not wipe it off with excessive force. Scratches on the filter may cause errors.
- 4. Sensing Object
- The Sensor Head cannot accurately measure the following types of objects: Transparent objects, objects with an extremely low reflection ratio, objects smaller than the spot diameter, objects with a large curvature, excessively inclined objects, etc.
- 5. The degree of protection is IP67, but do not use the Sensor Head in water, rain, or outdoors.

Amplifier Units

♠ WARNING

This Amplifier Unit is not designed or rated for ensuring safety of persons either directly or indirectly.



Do not use the Amplifier Unit with voltage in excess of the rated voltage.

Excess voltage may result in malfunction or fire.



Never use the Amplifier Unit with an AC power

Otherwise, explosion may result.



Precautions for Safe Use

The following precautions must be observed to ensure safe operation of the Amplifier Unit. Doing so may cause damage or fire.

- 1. Do not install the Amplifier Unit in the following locations.
- · Locations subject to direct sunlight
- · Locations subject to condensation due to high humidity
- · Locations subject to corrosive gas
- · Locations subject to vibration or mechanical shocks exceeding the rated values
- · Locations subject to exposure to water, oil, chemicals
- · Locations subject to stream
- Locations subjected to strong magnetic field or electric field
- 2. Do not use the Amplifier Unit in environments subject to flammable or explosive gases.
- 3. Do not use the Amplifier Unit in any atmosphere or environment that exceeds the ratings.
- 4. To secure the safety of operation and maintenance, do not install the Amplifier Unit close to high-voltage devices or power devices.
- 5. High-voltage lines and power lines must be wired separately from the Amplifier Unit. Wiring them together or placing them in the same duct may cause induction, resulting in malfunction or damage.
- 6. Do not apply any load exceeding the ratings. Otherwise, damage or fire may result.
- Do not short the load. Otherwise, damage or fire may result.
- 8. Do not use the Amplifier Unit if the case is damaged.
- **9.** Burn injury may occur. The Amplifier Unit surface temperature rises depending on application conditions, such as the ambient temperature and the power supply voltage. Use caution when operating or cleaning the Amplifier Unit.
- 10. When setting the sensor, be sure to check safety such as by stopping the equipment.
- .Be sure to turn off the power supply before connecting or disconnecting wires.
- 12.Do not attempt to disassemble, repair, or modify the Amplifier Unit in anv wav.
- 13. When disposing of the Amplifier Unit, treat it as industrial waste.

Precautions for Correct Use

- 1. Connect the load correctly.
- Do not miswire such as the polarity of the power supply.
- 3. Be sure to mount the unit to the DIN track until it clicks.
- 4. When using the Amplifier Units with Wire-saving Connectors, attach the protective stickers (provided with E3X-CN-series Connectors) on the unused power pins to prevent electrical shock and short circuiting.

Attach the protective cap when using a model with a connector for a Sensor Communications Unit.

Amplifier Unit with Wiresaving Connector



Amplifier Unit with Connector for Sensor Communications Unit

- 5. Use an extension cable with a minimum thickness of 0.3 mm² and less than 100 m long.
- 6. Do not apply the forces on the cord exceeding the following limits: Pull: 40N; torque: 0.1N·m; pressure: 20N; bending: 29.4N
- 7. Do not apply excessive force (9.8 N max.) such as tension, compression or torsion to the connector of the Sensor Head that is fixed to the Amplifier Unit.
- 8. Always keep the protective cover in place when using the Amplifier Unit. Not doing so may cause malfunction.
- 9. It may take time until the received light intensity and measured value become stable immediately after the power is turned on depending on use environment.
- 10. The Mobile Console E3X-MC11, E3X-MC11-SV2 and E3X-MC11-S cannot be connected.
- 11. The mutual interference prevention function does not work when in combination with E3C/E2C/E3X.
- 12.If the unit receives excessive sensor light, the mutual interference prevention function may not work properly, resulting in malfunction of the unit. In such case, increase the threshold. **13.**Standard models (E3NC-SA21/51/7/9)


The Sensor Communication Unit E3X-DRT21-S, E3X-CRT, E3X-ECT and E3NW cannot be connected.

Model for Sensor Communication Unit (E3NC-SA0)


The Sensor Communication Unit E3NW can be connected. E3X-DRT21-S, E3X-CRT, E3X-ECT cannot be connected.

- 14.If you notice an abnormal condition such as a strange odor, extreme heating of the unit, or smoke immediately stop using the product, turn off the power, and consult your dealer.
- 15.Do not use thinner, benzene, acetone, and lamp oil for cleaning.

Sensor Heads





Amplifier Units




Amplifier Units with Wire-saving Connectors

E3NC-SA7 E3NC-SA9





Amplifier Unit with Connector for Sensor Communications Unit E3NC-SA0




Accessories (Sold Separately)


Sensor Head Mounting Brackets

E39-L187






With E39-L187 Mounting Bracket Attached




E39-L188






With E39-L188 Mounting Bracket Attached



Wire-saving Connector

Master Connector E3X-CN21






*4-dia. cable with 4 conductors, Standard cable length: 2 m (Conductor cross-section: 0.2 mm² (AWG24), Insulation diameter: 1.1 mm)

Slave Connector E3X-CN22






*4-dia. cable with 2 conductors, Standard cable length: 2 m (Conductor cross-section: 0.2 mm² (AWG24), Insulation diameter: 1.1 mm)

Sensor I/O Connectors


Straight XS3F-M421-40□-A






L-shaped XS3F-M422-40□-A






Amplifier Unit Mounting Bracket E39-L143



DIN Track PFP-100N PFP-50N







Material: Aluminum

PFP-100N2









Material: Aluminum

End Plate PFP-M







Materials: Iron, zinc plating

Terms and Conditions Agreement

Read and understand this catalog.

Please read and understand this catalog before purchasing the products. Please consult your OMRON representative if you have any questions or comments.

Warranties.

- (a) Exclusive Warranty. Omron's exclusive warranty is that the Products will be free from defects in materials and workmanship for a period of twelve months from the date of sale by Omron (or such other period expressed in writing by Omron). Omron disclaims all other warranties, express or implied.
- (b) Limitations. OMRON MAKES NO WARRANTY OR REPRESENTATION, EXPRESS OR IMPLIED, ABOUT NON-INFRINGEMENT, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OF THE PRODUCTS. BUYER ACKNOWLEDGES THAT IT ALONE HAS DETERMINED THAT THE

PRODUCTS WILL SUITABLY MEET THE REQUIREMENTS OF THEIR INTENDED USE.

Omron further disclaims all warranties and responsibility of any type for claims or expenses based on infringement by the Products or otherwise of any intellectual property right. (c) Buyer Remedy. Omron's sole obligation hereunder shall be, at Omron's election, to (i) replace (in the form originally shipped with Buyer responsible for labor charges for removal or replacement thereof) the non-complying Product, (ii) repair the non-complying Product, or (iii) repay or credit Buyer an amount equal to the purchase price of the non-complying Product; provided that in no event shall Omron be responsible for warranty, repair, indemnity or any other claims or expenses regarding the Products unless Omron's analysis confirms that the Products were properly handled, stored, installed and maintained and not subject to contamination, abuse, misuse or inappropriate modification. Return of any Products by Buyer must be approved in writing by Omron before shipment. Omron Companies shall not be liable for the suitability or unsuitability or the results from the use of Products in combination with any electrical or electronic components, circuits, system assemblies or any other materials or substances or environments. Any advice, recommendations or information given orally or in writing, are not to be construed as an amendment or addition to the above warranty.

See http://www.omron.com/global/ or contact your Omron representative for published information.

Limitation on Liability; Etc.

OMRON COMPANIES SHALL NOT BE LIABLE FOR SPECIAL, INDIRECT, INCIDENTAL, OR CONSEQUENTIAL DAMAGES, LOSS OF PROFITS OR PRODUCTION OR COMMERCIAL LOSS IN ANY WAY CONNECTED WITH THE PRODUCTS, WHETHER SUCH CLAIM IS BASED IN CONTRACT, WARRANTY, NEGLIGENCE OR STRICT LIABILITY.

Further, in no event shall liability of Omron Companies exceed the individual price of the Product on which liability is asserted.

Suitability of Use.

Omron Companies shall not be responsible for conformity with any standards, codes or regulations which apply to the combination of the Product in the Buyer's application or use of the Product. At Buyer's request, Omron will provide applicable third party certification documents identifying ratings and limitations of use which apply to the Product. This information by itself is not sufficient for a complete determination of the suitability of the Product in combination with the end product, machine, system, or other application or use. Buyer shall be solely responsible for determining appropriateness of the particular Product with respect to Buyer's application, product or system. Buyer shall take application responsibility in all cases.

NEVER USE THE PRODUCT FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY OR IN LARGE QUANTITIES WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCT(S) IS PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.

Programmable Products.

Omron Companies shall not be responsible for the user's programming of a programmable Product, or any consequence thereof.

Performance Data.

Data presented in Omron Company websites, catalogs and other materials is provided as a guide for the user in determining suitability and does not constitute a warranty. It may represent the result of Omron's test conditions, and the user must correlate it to actual application requirements. Actual performance is subject to the Omron's Warranty and Limitations of Liability.

Change in Specifications.

Product specifications and accessories may be changed at any time based on improvements and other reasons. It is our practice to change part numbers when published ratings or features are changed, or when significant construction changes are made. However, some specifications of the Product may be changed without any notice. When in doubt, special part numbers may be assigned to fix or establish key specifications for your application. Please consult with your Omron's representative at any time to confirm actual specifications of purchased Product.

<u>Errors and Omissions.</u> <u>Information presented by Omron Companies has been checked and is believed to be accurate; however, no responsibility is accurate.</u> assumed for clerical, typographical or proofreading errors or omissions.

2013.10

In the interest of product improvement, specifications are subject to change without notice.

